
G1SLE
Mk2+ Rev A
CTCSS to TX
Net busy out
Gnd
Gnd
Gnd
MainsFail
+5v out
Spare AF in
Spare AF out
V supply
V supply
RSSI in
Aux AF in
RX AF in
RF to TX out
Pips out
TX key out
Hi/Lo pwr out
CTCSS Dec out
Net busy out
Net key in
Mute in
RC busy in
Disc RF in
RC RF in